

# v1.05 Firmware Release Notes

Keithley Instruments, Inc. 28775 Aurora Road Cleveland, Ohio 44139-1891 440-248-0400 • Fax: 440-248-6168 http://www.keithley.com

### **Contents**

| Contents                  | 1 |
|---------------------------|---|
| General Information       | 1 |
| Supported Models          |   |
| Installation Instructions | 1 |
| v1.05 Release             | 2 |
| Overview                  | 2 |
| Critical Fixes            | 2 |
| Non-Critical Fixes        | 2 |
| Enhancements              | 2 |
| v1.03 Release             | 2 |
| Overview                  | 2 |
| Critical Fixes            | 2 |
| Non-Critical Fixes        | 2 |
| Enhancements              | 3 |
| v1.02 Release             | 3 |
| Overview                  |   |
| Critical Fixes            |   |
| Non-Critical Fixes        | 3 |
| Enhancements              |   |
| v1.01 Release             |   |
| Overview                  | 4 |

## **General Information**

### Supported Models

This release note applies to the Keithley 2100 6 ½ Digit Multimeter.

### Installation Instructions

Detailed instructions are included in Chapter 4 of the Model 2100 User's Manual (Document Number: 2100-900-01B). The manual is available on the Product Information CD that ships with the Model 2100 Multimeter and is also available for download from the Keithley website at <a href="http://www.keithley.com/support/data?asset=50760">http://www.keithley.com/support/data?asset=50760</a>. Alternatively, Keithley factory upgrades can be arranged by calling your local Keithley support office.

### v1.05 Release

#### Overview

v1.05 was a maintenance release. It corrects one critical issue

#### Critical Fixes

ENG. Symptom:

DISC. Model 2100 with version 1.03 firmware does not accept zero calibration.

#### Resolution:

Update 2100 to accept zero calibration. Any unit with firmware version 1.03 will need to be updated to 1.05 prior to calibration.

### Non-Critical Fixes

There were no non-critical fixes included in this release. See the Critical Fixes section for more information about release content.

#### **Enhancements**

There were no enhancements included in this release.

### v1.04 Release

#### **Overview**

Internal working engineering release never formally released.

### v1.03 Release

#### **Overview**

v1.03 was a maintenance release. It corrects several non-critical issues

#### Critical Fixes

There were no critical fixes included in this release. See the Non-critical Fixes section for more information about release content.

#### Non-Critical Fixes

ENG. **Symptom:** 

DISC. When the user enters self-test from the front panel, the instrument generates Error +604.

#### Resolution:

The error is no longer generated when the 2100 performs a self-test.

ENG. **Symptom:** 

DISC. When the user selects the FREQ function, the Model 2100 would generate Error +603.

#### Resolution:

The error is no longer generated when the 2100 performs a self-test.

#### ENG. **Symptom:**

DISC.

The Model 2100 does not return to all default parameters upon receipt of "\*RST".

#### Resolution:

The Model 2100 restores all power-on default functions and values upon receipt of "\*RST".

#### **Enhancements**

There were no enhancements included in this release.

### v1.02 Release

#### Overview

v1.02 was an internal release.

#### Critical Fixes

ENG. **Symptom:** 

DISC.

The Model 2100 does not correctly measure temperature in RTD mode when the actual temperature is less than 0 degrees.

#### Resolution:

The multimeter now correctly measures temperature below 0 degrees.

#### Non-Critical Fixes

ENG. **Symptom:** 

DISC. Response to "\*IDN?" does not follow Keithley format standard.

#### Resolution:

Response to "\*IDN" query changed to "KEITHLEY INSTRUMENTS INC.,MODEL 2100 <system version>".

#### ENG. **Symptom:**

DISC.

When measuring 4W ohms, the multimeter displays "OVLD" if the Sense HI and Sense LO terminals are connected in reverse with respect to the Input HI and Input LO terminals.

#### Resolution:

The multimeter will now correctly display a negative resistance value when the Sense HI and Sense Lo terminals are connected in reverse with respect to the Input HI and Input Lo terminals.

### **Enhancements**

There were no enhancements included in this release.

# v1.01 Release

### Overview

This is the initial release, there are no critical problems to document in this version.