



Keithley Instruments

28775 Aurora Road Cleveland, Ohio 44139-1891 1-888-935-5595 www.keithley.com

Version A07 Firmware Release Notes

Contents

General Information	
Supported models	
Installation instructions	2
Upgrade considerations for 6487 models	
A07 Release	
Overview	
Critical Fixes	
Noncritical Fixes	3
Enhancements	3
Known Issues	3

General Information

Supported models

This firmware is intended for use on the following Keithley Instruments product models:

6487

Installation instructions

To aid in installation, the Flash Wizard software and Firmware file are bundled together as one file. This bundled package is located on the Keithley website at www.Keithley.com. Search for Firmware by Model 6487 under the support tab.

Upgrade considerations for 6487 models

Upgrade is available for those who wish to have the latest firmware enhancements and upgrades installed on their instrument. Upgrade to A07 as needed to address any specific problems listed in the various sections below.

2 6487-800A07

A07 Release

Overview

Upgrade is available for those who wish to have the latest firmware enhancements and fixes installed on their instrument. Upgrade from A01 through A06 to A07 as needed to address any specific problems listed below.

A07 Release: Overview

Critical Fixes

PR39595 Symptom:

Intermittent GPIB operation in DDC language mode.

Resolution:

The error no longer occurs

Noncritical Fixes

There were no noncritical fixes included in this release.

Enhancements

There were no enhancements included in this release.

Known Issues

There were no known issues included in this release.

6487-800A07 3