

Keithley Instruments, Inc.
28775 Aurora Road
Cleveland, Ohio 44139
1-888-KEITHLEY
www.keithley.com

GPIB Driver Compatibility

General

All GPIB interface drivers can be installed before or after ACS Basic has been installed. The order of installation will not affect the functionality of the software.

Keithley Instruments, Inc.

Uninstalling or reinstalling KITE or Keithley GPIB interface drivers (on a system that has ACS Basic already installed) may cause ACS Basic to function incorrectly due to .dll errors. To resolve this issue please reinstall ACS Basic every time KITE or Keithley GPIB interface drivers are uninstalled or reinstalled.

National Instruments

When installing the NI GPIB interface driver, version NI-488.2 v2.7.3 or above, by default the NI VISA driver option is not installed. Some instruments (controlled via PTM's) may not respond if the NI VISA driver is missing. Please ensure that the NI VISA option is enabled during installation of the NI GPIB interface driver.

Uninstalling or reinstalling NI GPIB interface drivers or NI VISA drivers (on a system that has ACS Basic already installed) may cause ACS Basic to function incorrectly due to .dll errors. To resolve this issue please reinstall ACS Basic every time NI GPIB interface drivers or NI VISA drivers are uninstalled or reinstalled.

CEC

ACS Basic supports CEC488 GPIB drivers 8.2 or above. Please upgrade older drivers to ensure compatibility.

Uninstalling or reinstalling CEC GPIB interface drivers (on a system that has ACS Basic already installed) may cause ACS Basic to function incorrectly due to .dll errors. To resolve this issue please reinstall ACS Basic every time CEC GPIB interface drivers are uninstalled or reinstalled.