

May 29, 2012

Keithley CD V2.4 Release Notes:

1. The KUSB3100 driver and firmware were updated.
2. The MATLAB DAQ Adapter SampleRate property bug was fixed.
3. The OEM Setup was updated to check for the .NET Framework; if it is not installed, the .NET OL components are not installed.
4. quickDAQ was updated to use the latest OL.NET and synchronous buffer done.
5. Support for Microsoft Developer's Studio 2010 was added.